



- Notes:**
- Before drilling check the hole pattern chart (H04). See also the appropriate installation template (H09, H11, H12, or H13).
 - The maximum door-to-frame gap is $\frac{3}{16}$ "
 - Allow $\frac{3}{64}$ " clearance for the strike box thickness.
 - For metal doors, lock case support is required from the door manufacturer.
 - Tap for a #12-24 machine screw or drill for #12 wood screw (a combination screw is supplied).
 - Magnetic strike box applies only with IDH option.
 - Lock case holes:**
 - 1 Cylinder hole— $1\frac{1}{4}$ " dia *
 - 2 Hotel indicator hole— $1\frac{1}{2}$ " dia.
 - 3 Knob hole— $7\frac{7}{8}$ " dia.
 - 4 Thru-bolt holes— $3\frac{3}{8}$ " dia. (two required)
- *For 36H and 37H Series drill a $1\frac{3}{4}$ " dia. hole.

Title Installation Specifications for 34HW-37HW Electrified Mortise Locks					BEST ACCESS SYSTEMS	
Series 34HW- 37HW	Backset 2 3/4"	Functions EWEU/EL, WWEU/EL, YEU/EL	Trim style A, B, C, D, H, J, M, N, S	Door thickness 1 3/4"-5"	Rev date 06/2003	Template number W22
						Rev B