


Keyed visual indicator trim

Installation Instructions

1 Installing turn knob cam

- 1.1 Begin with lock in locked position.
- 1.2 Position mounting bracket against door.
- 1.3 Insert turn knob cam w/cam facing down.
NOTE: Inside escutcheon will surface mount; does not use through-bolt.




Document translations available.
Scan for product details and downloads.
Call 1-800-392-5209 or visit
<https://dhwsupport.dormakaba.com/hc/en-us>
for assistance and warranty information.

WARNING! This Manufacturer advises that no lock can provide complete security by itself. This lock may be defeated by forcible or technical means, or evaded by entry elsewhere on the property. No lock can substitute for caution, awareness of your environment, and common sense. Builder's hardware is available in multiple performance grades to suit the application. In order to enhance security and reduce risk, you should consult a qualified locksmith or other security professional.

BEST is a trademark of dormakaba USA Inc. ©2026. All rights reserved.


2 Installing VIN slider

- 2.1 Position VIN slider on top of turn knob cam resting on support legs if applicable.



3 Installing trim

- 3.1 Position escutcheon over indicator and install cylinder and levers as normal.




T95327_C

Keyed visual indicator trim

Installation Instructions

1 Installing turn knob cam

- 1.1 Begin with lock in locked position.
- 1.2 Position mounting bracket against door.
- 1.3 Insert turn knob cam w/cam facing down.
NOTE: Inside escutcheon will surface mount; does not use through-bolt.




Document translations available.
Scan for product details and downloads.
Call 1-800-392-5209 or visit
<https://dhwsupport.dormakaba.com/hc/en-us>
for assistance and warranty information.

WARNING! This Manufacturer advises that no lock can provide complete security by itself. This lock may be defeated by forcible or technical means, or evaded by entry elsewhere on the property. No lock can substitute for caution, awareness of your environment, and common sense. Builder's hardware is available in multiple performance grades to suit the application. In order to enhance security and reduce risk, you should consult a qualified locksmith or other security professional.

BEST is a trademark of dormakaba USA Inc. ©2026. All rights reserved.


2 Installing VIN slider

- 2.1 Position VIN slider on top of turn knob cam resting on support legs if applicable.



3 Installing trim

- 3.1 Position escutcheon over indicator and install cylinder and levers as normal.



T95327_C



dormakaba Group

Keyed visual indicator trim

Installation Instructions



Document translations available.

Scan for product details and downloads.

Call 1-800-392-5209 or visit

<https://dhwsupport.dormakaba.com/hc/en-us>

for assistance and warranty information.

⚠ WARNING! This Manufacturer advises that no lock can provide complete security by itself. This lock may be defeated by forcible or technical means, or evaded by entry elsewhere on the property. No lock can substitute for caution, awareness of your environment, and common sense. Builder's hardware is available in multiple performance grades to suit the application. In order to enhance security and reduce risk, you should consult a qualified locksmith or other security professional.

BEST est une marque déposée de dormakaba USA Inc. ©2026. Tous droits réservés.

T95327_C



dormakaba Group

Keyed visual indicator trim

Installation Instructions



Document translations available.

Scan for product details and downloads.

Call 1-800-392-5209 or visit

<https://dhwsupport.dormakaba.com/hc/en-us>

for assistance and warranty information.

⚠ WARNING! This Manufacturer advises that no lock can provide complete security by itself. This lock may be defeated by forcible or technical means, or evaded by entry elsewhere on the property. No lock can substitute for caution, awareness of your environment, and common sense. Builder's hardware is available in multiple performance grades to suit the application. In order to enhance security and reduce risk, you should consult a qualified locksmith or other security professional.

BEST est une marque déposée de dormakaba USA Inc. ©2025. Tous droits réservés.

T95327_C



dormakaba Group

Keyed visual indicator trim

Installation Instructions



Document translations available.

Scan for product details and downloads.

Call 1-800-392-5209 or visit

<https://dhwsupport.dormakaba.com/hc/en-us>

for assistance and warranty information.

⚠ WARNING! This Manufacturer advises that no lock can provide complete security by itself. This lock may be defeated by forcible or technical means, or evaded by entry elsewhere on the property. No lock can substitute for caution, awareness of your environment, and common sense. Builder's hardware is available in multiple performance grades to suit the application. In order to enhance security and reduce risk, you should consult a qualified locksmith or other security professional.

BEST es una marca registrada de dormakaba USA Inc. ©2026. Todos los derechos reservados.

T95327_C



dormakaba Group

Keyed visual indicator trim

Installation Instructions



Document translations available.

Scan for product details and downloads.

Call 1-800-392-5209 or visit

<https://dhwsupport.dormakaba.com/hc/en-us>

for assistance and warranty information.

⚠ WARNING! This Manufacturer advises that no lock can provide complete security by itself. This lock may be defeated by forcible or technical means, or evaded by entry elsewhere on the property. No lock can substitute for caution, awareness of your environment, and common sense. Builder's hardware is available in multiple performance grades to suit the application. In order to enhance security and reduce risk, you should consult a qualified locksmith or other security professional.

BEST es una marca registrada de dormakaba USA Inc. ©2025. Todos los derechos reservados.

T95327_C